



**LASER AMMO**  
TRAINING TECHNOLOGIES

## SureStrike™ Bore Sight Cap User Guide:

SureStrike Bore Sight Cap lets you convert your standard 9mm SureStrike laser dry fire training system to a Bore Sighting tool.

### Step 1:

Unscrew the back and front end of your laser bullet and separate them. Keep your battery.



### Step 2:

Place your back cap aside. Replace your dry fire cap with bore sight cap. Insert the battery pack into the laser bullet according to the drawing.



### Step 3:

Reassemble your laser bullet carefully. Proceed to load the bullet into your gun as instructed in the SureStrike user steps 3 – 8.



\* We strongly recommend that the battery be removed when the laser bullet is not in use to prolong your battery's life.